














TS 5000
TS 5000 S
TS 5000 SoftClose




107934-04

GEZE




6




- 2x Ø 5
- 2x M5

7




8




i+

TS 5000 S




i+

TS 5000 SoftClose



9



i

